

Dartron

Issuing Entity:
Dartron Industries, Inc

P. O. Box 13114
Salem, Oregon 97309
Phone: 503-362-2341
Fax: 503-362-2536

www.dartronrides.com

Bulletin # BU0201PRO1

Release Date: 01-15-2002

Effective Date: 01-15-2002

Supercedes: N/A

Completion Date: N/A

Page 1 of 1

SERVICE BULLETIN

Ride Manufacturer: Man-Co Mfg. Kilinski Mfg. Affected Production Dates: All
Frank Hrubetz Co.

Ride Name: Round Up, Paratrooper	Affected Serial #'s All
Model # All	

Abstract of Issue: Man-Co Mfg, issued bulletin BU-136 MC on September 8, 1988 concerning the annual inspection procedures required on all hubs for Paratroopers and Round Ups manufactured by Man-Co Mfg., Kilinski Mfg., and Frank Hrubetz Co. Dartron has designed a hub for Paratroopers and Round-Ups, which address the areas of concern on the above hubs. The areas of concern are the welds between a sleeve that was installed over the top of the hub center. Dartrons design eliminates the sleeve and replaces the main pipe with a tube that has a wall that is thicker than the main pipe sleeve combined. This design eliminates the suspect sleeve and welds. The Dartron hub has been in service for over ten year without any problems reported or observed. Recall Bulletin BU-136 MC mentioned above pertains only to hubs manufactured by Man-Co, Kilinski and Hrubetz. It is not valid for Rounds Up and Paratrooper hubs manufactured by Dartron.

Reason for release: It has come to the attention of Dartron Industries that unnecessary inspections are being performed on new Paratrooper and Round Up hubs. Dartron position on this matter is that Round Up and Paratrooper hubs manufactured by Dartron, do not require annual NDT inspection.

Action to be taken: To determine whether a Round Up or Paratrooper hub was manufactured by Dartron conduct a visual inspection. If the hub is on a Paratrooper and is a "split type" it does not require the NDT inspection. A "split" type hub allows all sweeps to be rotated to the rear of the trailer for transport. If it is not a "split" type hub inspect for the sleeve as shown below.

Detail of issue: Below is the sketch indicating the difference between the old style hub and the Dartron hub.

